**MOTOROLA** SOLUTIONS

## Professional Series Portable Firmware Upgrade Kit R05.17.01 Customer Release Notes

# NOTE: Professional CPS R06.12.05 and later is recommended with this firmware.

This release of radio firmware <u>only supports the Popular and Preferred</u> families of Professional Series Portable Radios. All bands in these families are supported. For any questions, please contact Customer Resources at 1-800-927-2744.

### I. <u>Enhancements</u>

#### Item #1: Portable Radio Codeplug: ARTS™ Features

Release R05.17.01 modifies the codeplug to enable the configuration of ARTS<sup>™</sup> features. Professional Radio CPS R06.12.05 is <u>required</u> to configure these features.

#### II. <u>Corrections</u>

#### Item #1: Conventional Radio Shows Unprogrammed After Exit From Test Mode

If the channel is changed while in test mode, the radio channel is also changed in normal mode. This can lead to issues where the radio is set to an unprogrammed channel upon exiting test mode.

#### Item #2: Radio Unable to TX Audio from Accessory Connector

After issue of generic command \$01, the radio is unable to TX audio from the accessory connector pins FLAT\_TX\_AUDIO and EXT\_MIC\_AUDIO.

#### III. Known Issues

None

MOTOROLA SOLUTIONS and the Stylized M Logo are registered in the U.S. Patent & Trademark Office. All other product or service names are the property of their respective owners. © Motorola Solutions, Inc. 2011.